

Tom Collins

From: ted <ted@fullerelectronics.com>
Sent: Friday, December 05, 2014 9:10 AM
To: Tom Collins
Subject: Re: transmitter

Tom,
It may be powering itself back due to an antenna issue of some kind, or something internal. It it for certain that this started after the move?

----- Original Message -----

From: [Tom Collins](#)
To: [Ted Fuller](#)
Sent: Friday, December 05, 2014 8:27 AM
Subject: transmitter

I was informed yesterday by Mikey that he found the transmitter running at about 700 Watts on Sunday evening .. Craig told me the same thing yesterday except it was about 800 .. Steve told me this morning it was around 700. Planned to discuss this with you yesterday when you over but I was informed later in the day you were not coming. I am not sure but prior to that transmitter being moved it appeared to be fairly stable .. have no idea if moving it could cause the problem but wanted you to be aware.

Have a great day.

Tom Collins
336 239-1359